



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: March 15, 2009

Reviewed: PPB

Mine Name: Island Rock 1	Permit Number: S/045/0066
Operator Name: John Bleazard	Inspection Date: 10-29-2008
Inspector(s): L. Heppler	Time: 5:00 PM
Other Participants: none	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 10-13-2008 **Bond Amount:** \$2500 **Permit fee** is delinquent

Purpose of Inspection: Routine annual inspection

Inspection Summary: Several bedrock pits in the area. One area has been regraded. No effort has been done to stockpile topsoil or revegetation. There is numerous abandoned equipment, mostly track hoes, but also includes an old dragline and 3 trucks.

Photos were taken to document site conditions.

Conclusions and Recommendations: Equipment needs to be salvaged. Bond needs to be escalated. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: John Bleazard

O:\M045-Tooele\S0450066-IslandRock\inspections\insp_10292008.doc



Abandoned Trucks



Abandoned Dragline



Abandoned trackhoe



Abandoned trackhoe